


Wirelynx Powerline Carrier Hookup Diagrams




Wirelynx Hookup Diagrams-2011-REV2.vsd

Wirelynx Powerline Carrier Wiring Diagrams		REVISIONS	
		NO.	DATE
DATE ORIGINAL	SCALE		
5/12/11	N/A		
LATEST REVISION	JOB NO.	CHECKED	DRAWN
Rev 2			WHB

Brayden Automation Corp.
 6230 Aviation Circle
 Loveland, CO 80538
 (970)461-9600
 (970)461-9605 fax
www.solidstateinstruments.com


F

120/208VAC
 Three-Phase 4 Wire Wye
 120VAC Phase to Neutral
 208VAC Phase to Phase
 Phases need not be identified;
 Neutral is available at xmtr & receivers.



G

277/480VAC
 Three-Phase 4 Wire Wye
 277VAC Phase to Neutral
 480VAC Phase to Phase
 Phases need not be identified;
 Neutral must be available at xmtr & receivers



Wirelynx Hookup Diagrams-2011-REV2.vsd

Wirelynx Powerline
 Carrier Wiring
 Diagrams

DATE ORIGINAL
 5/12/11

SCALE
 N/A

LATEST REVISION
 Rev 2

JOB NO.

REVISIONS

NO.	DATE	DESCRIPTION






CHECKED

DRAWN

WHB

Brayden Automation Corp.

6230 Aviation Circle
 Loveland, CO 80538
 (970)461-9600
 (970)461-9605 fax
 www.solidstateinstruments.com



Wirelynx Hookup Diagrams-2011-REV2.vsd

Wirelynx Powerline Carrier Wiring Diagrams		REVISIONS		
		NO.	DATE	DESCRIPTION
DATE ORIGINAL	SCALE			
5/12/11	N/A			
LATEST REVISION	JOB NO.	CHECKED	DRAWN	
Rev 2			WHB	

Brayden Automation Corp.
6230 Aviation Circle
Loveland, CO 80538
(970)461-9600
(970)461-9605 fax
www.solidstateinstruments.com